

Am. 10.10.

WRECK BOX

No. 16. Bottom.

Wreck 16

1

Received by Chief Ship Surveyor 24.5.18

Received from Chief Ship Surveyor 25 MAY 1918

VESSEL'S NAME Success Galway Castle

Rpt. hon No. 80843

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

DAMAGE.

Damage through Grounding

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed .....							
Removed and faired or repaired.....							
Faired or repaired in place.....							

Other items:-


Vessel examined in dry dock, bottom cleaned & coated & the temporary repairs to bottom <sup>& sides</sup> plating, stanchions, madders &c effected at Port Natal. Examined & found satisfactory, and in the Surveyors opinion permanent repairs may be deferred until a more convenient opportunity. The Special Survey, due 10.15 & port held has not been advanced at this time.

It is submitted the vessel is worthy to remain as classed with

record of Survey as recommended action be deferred

The Surveyors request to state whether, in view of the year of grace having expired in November 1916, the vessel has now been generally examined & whether in their opinion the record of Examined 5.18 should be made in this case. The Surveyors state in their opinion a record of 5.18 is not might be assigned.

It is submitted action be deferred & Examined 5.18 recorded as recommended



© 2020

Lloyd's Register Foundation

W896-0018