

2m, 10, 15.

Wreck 15.

WRECK  
No. 15

8

Sent to Chief Ship Surveyor 1. 11. 16

Received from Chief Ship Surveyor NOV 16

VESSEL'S NAME Steel S. S. "Matarazzo" Rpt. Cff No. 39125

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey


DAMAGE.

This vessel is reported by the Cardiff Surveyor to have sustained damage to shell plating etc through striking a pier head. She has been examined in drydock. Temporary repairs have been effected to his satisfaction to enable her to proceed on her voyage to

The Surveyor recommends that permanent repairs be effected at the first convenient opportunity

It is submitted the vessel appears worthy to remain as classed subject as above.

As now - Subject



© 2020

Lloyd's Register  
Foundation

W898-0013