

F.E.

Received by Chief Ship Surveyor 20/11/06

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME St. S. Ennisbrook Rpt. Sea No. 23042

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	$\frac{2}{30}$	Proportions
Spar Sheerstrake . .	✓	✓
Description of Framing: <u>Deep (Zed framed) increased to compound</u> (viz., ordinary, deep, zed, channel or bulb-angle) <u>for construction of middle deck &amp; beams.</u>		

RETAIN

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed +100A1 (Shul) as recommended.

+100A1 (Shul)

10% (Sea) & dup framing

KB = CUL DB 110' x E 22' x 128' 6896 APT 546

F.N. SBA. Cinn. Lloyds A16.0. 030' B92' F28'

RBT



20/11/06 2020

Lloyd's Register Foundation  
W898-0016