

REPORT OF TOTAL LOSS, CASUALTY, &c.

No. 84856 in R. B. Wreck Book, p. 96/40. Date of writing this report _____ 19__

Vessel's Name S.S. Timavo (and RMC) of Trieste Tons {Gross 1549
Net 4731

Built at Trieste When 1920 8 Casualty notice sent to Owner Owner's reply

Owner's Name Societa Anonima di Navigazione Lloyd Triestino
Address Palazzo Lloyd, Trieste

Case previously before Classing Committee.	Date	Particulars of Classification.	
	Last Minute		+ 100 A.I. Sheer ak. with freeboard 5,40. S.S. Gen. No. 3-12, 32 S.S. Ai. No. 1-37

Date of Casualty 11th June, 1940

Precis of particulars of Casualty Intercepted by South African Air Force plane 160 miles north of Durban on the 11th June, 1940. Beached herself and broke her back on the 22nd June, 1940.

SOURCE OF INFORMATION.

TIMAVO.—Durban, June 11. — Italian steamers GERUSALEMME and Timavo, which left Durban yesterday, have been beached by their crews. The GERUSALEMME went aground after she was sighted by an armed merchant cruiser near Cape Oro, on the Union Portuguese border. The Timavo was overtaken by a South African Air Force plane at Cape Vidal, 160 miles north of Durban.—Reuter.

LL 12/6

TIMAVO.—Durban, June 12. — The crew of the Italian steamer Timavo, which was beached by her crew yesterday, were captured to-day. They were trying to make for the Portuguese border.—Reuter.

LL 13/6

TIMAVO.—Durban, July 10. — Steamer Timavo purposely ran herself aground and on June 22 broke her back, now in two separate parts. No salvage attempted and considered impracticable.—Lloyd's Agent per Salvage Association.

LL 12/7

TIMAVO.—Durban, July 17. — Steamer Timavo: Authorities advise offer received, but vessel broke up and salvage not possible.—Lloyd's Agent per Salvage Association.

LL 19/7

and
CL 12/6, 13/6, 14/6, 21/6, 12/7,
17/7 and 19/7

R. SECTION No. 79

Suggested Record
Date of Committee _____
Committee's Minute _____

OMIT ~~ED~~ FROM R.B.
TUE, 27 AUG 1940
OMIT ~~ED~~ FROM R.B.



© 2020
Lloyd's Register
Foundation

W90-0164