

3m.7.14.

WRECK BOX
No. 18

Wreck Box No 18

3-BEC 1915 1

Received by Chief Ship Surveyor 2.12.15

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S. S. Hans Jensen Rpt. Cpn No. 4824

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report. 24/5/92.)

DAMAGE.

Nature of Survey

Damage through Cause not stated

now repaired as follows:-

	Plates	Frames	R.Frames	Floors	Beams	Str.Plates	Dk.Plates
Renewed.....							
Removed and faired or repaired.....	2						
Faired or repaired in place.....	1	2					

Other items:-

Vessel examined in dry dock.
Bottom cleaned and coated.
Minor repairs effected.

It is submitted the vessel is worthy to remain as classed with record of Survey 11.15 as recommended

100 A.I.
11.15 Els

M.
A.P.
3.12.15



© 2020

Lloyd's Register
Foundation

10m.1.15.
are requested not to