

WRECK BOX

No.

16 (Bottom)

Surveyors 1. 1. 14

Received from Chief Surveyors

NAME H. S. Pulani

Report

LW

No. 70650

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92

Survey

Condition

When due

Indented plating to be paired at  
next dry docking.

W. H. J. J.  
1. 1. 14



© 2020

Lloyd's Register  
Foundation