

Wreck 15

WRECK BOX  
No. 15 70h

3

Received by Chief Ship Surveyor 1.6.15

Received from Chief Ship Surveyor

VESSEL'S NAME *Shulss Ethiope*

Rpt. *Shl*

No. 28527

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey S.S. No. 2 AND DAMAGE.

Damage through *Cause not stated*

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed .....	1						
Removed and faired or repaired.....	2						
Faired or repaired in place.....	3						


Other items:-

*Bottom & under cleaned & coated*

The *Completed* S.S. No. 2 has also been ~~had~~ and following repairs done due to wear and tear:-

It is submitted the vessel is worthy to remain classed with record of Survey *5-15* and notation of *SS 1012 No 2-15* as recommended. *without special condition.*

*100% 1. Sp. on with freeboard*  
*5-15 1012*  
*SS 1012 No 2-15*



© 2021  
Lloyd's Register  
Foundation  
W 911-0124