

4m, 10, 15.

Wrecks

8. Bottom

1

Received by Chief Ship Surveyor 8.7.18

Received from Chief Ship Surveyor

-9 JUL 1918

VESSEL'S NAME

Sheels Chicago

Rpt.

Shel

No. 305-93

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

DAMAGE.

Damage through

striking some submerged object - & striking quay wall

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							
Removed and faired or repaired							
Faired or repaired in place	4						

Other items:-

Vessel examined in dry dock, riveting & caulking
reshaunted as required & bottom cleaned & coated

Arrangement for carrying out work not yet
completed

It is submitted the vessel is worthy to remain as classed with

record of Survey 6.18 as recommended

100A.1.

6.18 Shel

8718

© 2020

Lloyd's Register
Foundation

W920-0024