

WRECK BOX  
No. 1070

1

Received by Chief Ship Surveyor

1.5.14

Received from Chief Ship Surveyor

VESSEL'S NAME

Steel's Combe

Rpt.

Low

No. 27737

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

DAMAGE.

Damage through

Striking some submerged object.

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed .....	8	3	1	1			
Removed and faired or repaired.....	9			1			
Faired or repaired in place.....	9	34	4	3			

Other items:-

Vessel examined in dry dock, bottom  
cleaned & coated, and sundry minor repairs  
carried out

It is submitted the vessel is worthy to remain as classed with  
record of Survey 4.15 as recommended

100A-1.

4.15 Low



© 2021

Lloyd's Register  
Foundation

W922-0116