

C O P Y

Lloyd's Register of Shipping.



Port SHIMODA

4th December 1939.

This is to Certify that

M. Kamakura.

the undersigned Surveyor to this Society did at the request of

the Master, survey the Single Screw Steamer "V I D O V D A H", 5586 tons gross, of Dubrovnik, on the 3rd December 1939 whilst the vessel lay afloat off Wakamatsu, for the purpose of ascertaining the nature and extent of damage stated to have been caused by propeller touching quay of the Asahi Glass Works, Ltd., (Makiyama wharf) at Wakamatsu, on the 2nd December 1939 whilst the vessel was leaving the wharf for Milke.

For further particulars see Log Books.

The undersigned upon examination.

FOUND.

RECOMMENDED.

Propeller (cast iron solid).

One blade broken at tip eastern side,
about 60 centimeter by 13 centimeter.

To be properly repaired
or renewed.

Nothing done for repairs at this time.

The vessel is in my opinion, so far as the propeller damage is concerned in safe working condition.

It is recommended that the above damage repairs be carried out at the Owners convenience.

Fee-----25-0-0
Sundry fee- 2-2-0

M. Kamakura.

SURVEYOR TO LLOYD'S REGISTER.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
“While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.”