

COPY.

Lloyd's Register of Shipping 1940



Port SHIMONOSEKI.

4th December 1939.

This is to Certify that I have

Surveyed the ^{Part}~~Boiler~~ and Machinery of the Single Screw Steamer

"V I D O V D A N", 5586 tons gross, of Dubrovnik. No. 36093 in the Register Book. On account of propeller damage sustained on the 2nd December 1939.

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I have

Recommended that the ^{Present} record of ~~LMC~~

be ~~made in~~ ^{retained} the Register Book in the case of this vessel. Subject

to Propeller being properly repaired or renewed at the Owner's convenience.


H. I. Kamakura.

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

B1.)—10m, 8, 38. (MADE IN ENGLAND.)



Lloyd's Register
Foundation

W93-0119