

ived by Chief Ship Surveyor Y.S.P.

Received from Chief Ship Surveyor MAY 1917

VESSEL'S NAME Steel S. S. Colbert Rpt. Msl No. 4555

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey Part 33 no 2

It is submitted that before this case receives consideration the Surveyor's attention should be drawn to his report No 4343 & he should be requested to state whether the cables have now been repaired & also the number of anchors now on board as this information is not given in his report

Classing Letter.

11/5/17

M
A.T.
Y.S.P.

© 2021



Lloyd's Register
Foundation

W422-0114