

John Green.
Crown Chain and Anchor Works,
Old Hill.
Staffordshire.

TELEPHONE N° 14, CRADLEY.
PRIVATE N° 156 STOURBRIDGE.
CODE 5TH EDITION A.B.C.

16th June 1915.

Copy of letter to:-

Messrs Ropner & Sons Ltd.

Stockton on Tees.

No 501.

I am very much surprised to receive your telegram saying
Lloyds Surveyor will not pass the Anchors on account of them being
light collectively, which works out at under one quarter per
this to my mind is a negligible quantity and ought not to make
ference, if after putting this to the Surveyor he will not pass
anchors, please write to Lloyds and explain the case fully to them
have no doubt but they will allow the Surveyor to pass them.
so busy with Admiralty service Anchors I cannot possibly replace
considerable time.

Yours faithfully,

John Green
per [Signature]



© 2020

Lloyd's Register
Foundation

W934-1026