

RETAIN

OF PORT SAID.

15,th. APRIL. 1919.

JAMES MACVEY.

ers THE PORT SAID & SUEZ COAL CO. proceed on board the
" CHARLES TELLIER ", to ascertain the nature and extent of
damage, stated to have been caused on March 1st, while vessel
towing barges between BASSRA & BANDER ABBAS.
Other particulars see log and protest.

Age. Abreast of engine room, starboard side,
Sheer strake, two plates dented, and two rivets
sheered in gusset.
Strake below, one plate dented.
Abreast No 3 hatch.
Bulwark bulb torn.
Bulwark plate dented.
Sheer strake, one plate dented.
1st. strake below, one plate dented.
2nd. " " one plate dented.

There was no flaws in the plates.

One lifeboat damaged.

recommend the lifeboat to be repaired, and gusset plate
ltd.

e 24.4.0.

James Macvey

Surveyor to Lloyd's Register



© 2020

Lloyd's Register
Foundation