

24 FEB 1917

Received by Chief Ship Surveyor 23. 2. 17

Received from Chief Ship Surveyor

VESSEL'S NAME Stl.S.S. "CRISPIN".

Rpt.

Bry.

No. 15963

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

*General Examination 1st SS No 2 Due 12.15 p.m.*

The 1st Special Survey No.2 which became due 12.15 has been partly held.

The class of this vessel is subject to some damage through striking a wharf being repaired.

Action has been deferred from time to time, the vessel being on Government service.

On the 13th inst the Liverpool Surveyors were informed that it was noted the steamer was under Government control, and was to sail in three or four days, and in the circumstances, it was considered that a general examination of the steamer should be made, and provided this be done with satisfactory results, the Committee would be agreeable to the completion of the Special Survey No.2 standing over for the present; and the Surveyors were requested to inform the Owners accordingly.

*The Barry Surveyors were also informed. (Note at Barry)*  
The Barry Surveyors now report the vessel has been placed in dry dock, the bottom cleaned, examined and coated.

The temporary repairs to damage, referred to above, examined and found satisfactory.

The decks, 'tween decks, masts, holds, hatches, equipment, steering gear, E & B space, examined as far as possible and found in good condition.

The vessel being generally in good condition, in the Surveyors' opinion the completion of the Special Survey No.2 might be deferred for the present.



WRITE NOW



11 top

(2)

Stl.S.S. "CRISPIN" (Cont.)

The year of grace expired 12. 16.

It is submitted action be deferred.



23. 2. 17



© 2020

Lloyd's Register  
Foundation

W942-01232/2