

Lieut. Rayton Dixon Tis. No. 1534
("Crispin")

Submitted the Middlesbrough Surveyors should be informed that Mr. Jesse Williams - Principal Outdoor Surveyor in London has held a survey upon the land steering beam of the S.S. "Crispin" this day and he reports his concurrence in the Middlesbrough Surveyors recommendation as regards the support to spindle of same.

Mr. Williams was informed on board the vessel that the owners have arranged with the Builders for the latter to fit the support, as recommended, on the vessel's return from her present intended voyage in March next.

The Middlesbrough Surveyors should therefore forward the 1st Entry Report of the vessel to this Office

Mr. G. R. O'N
Ans. 72

J.H.

18/12/07

B 14/12/07

C.B.



© 2020

Lloyd's Register
Foundation

W942-0128