

Messrs. Sir Raylton Dixon & Co's S.S. No 534 - "Crispin"

Submitted the Middlesbrough Surveyors should be informed that in order for the S.S. "Crispin". - Mess^{rs} Sir Raylton Dixon & Co's S.S. No 534 - to be eligible for the Society's Classification it is necessary that the spindles of the hand steering gear should be efficiently supported to their satisfaction and that the ~~usual~~ generally other details in the vessel's construction & fittings should be favourably reported upon by them.

The Surveyors should inform the builders accordingly

J.H.L. 7/12/07

C.B.

12.07

7.12.



© 2020

Lloyd's Register
Foundation

W942-0133