

Date of writing Report 28th Jan'y 1916 When handed in at Local Office 28th Jan'y 1916 Port of CARDIFF

TONNAGE:—		Built at	Sunderland	By whom	J. Priestman & Co.	When	1915	YEAR.	MONTH.
GROSS	3689	Owners	C & W. Williams & Co.	Port belonging to	London				
UNDER DECK	3488	Owners' Address	(if not already recorded in Appendix to Register Book).						
NET	2205								

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.		CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years since last Survey expired.	Machinery and Boiler Surveys (including date of N.B., if any).
Last Report, No. 18152 Port <i>NY</i>		+ 100 A.1	+	L.M.C.

Medical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the use of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs amount of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; & besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the placement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? Was a damage report made by anyone else? If so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR boeking

Bottom cleaned, examined and recoated, one plate on starboard bilge at after end of No 1 hold slightly indented, riveting and caulking in way of same overhauled. Starboard Lascar pipe renewed on account fracture caused in stowing anchor.

NARY OF DAMAGE REPAIRS :—		Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								


ENT CONDITION OF THE		Stringers		Dblng. Plates under Soundng Pipes.		Copper, or I.M. of Wood Vessels	
ag of Decks	Inner Bottom Plating	Engine Room Skylights	(State if on Fell.)	When put on, Month
rays	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	Year	
gs	State if Tanks now tested	Couppers	Boats
& Fastenings	Bulkheads	Cargo Hatchways	Masts, Yards, &c.
Plating	Ceiling	Hatches	Condition, how ascertained
g of ditto	Cement or Asphalt	Planking	(State if wedges removed)
ooks & Crutches	(State which.)	of Wood Vessels	Sails
ns	Rudder	Caulking	Equipment letter
Frames	Steering gear and its connections	Treenails	Anchors, No. of
s	Windlass	Breasthooks & Stems	Cables (State if now ranged)
	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches	length
	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings	(on board)
	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places	Rule length
	Stringers, Clamps & Shelves	Hawser & Warps
	Salting	Standing & Running Riggng

eral Observations, Opinion as to Class, Recommendation, &c. :—


State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example :—“.....to remain as now classed in the Register Book *without fresh record of Survey*,” “to remain as classed and to have record of survey, 1,15,” or “to remain as classed and to have record of survey, 1,15, and the notations of *ss No. 1-15 and ptND15, &c.*”

This vessel is in my opinion eligible to remain as classed and have record of survey 1.16

Survey Fee (per Section 88)	£	:	:	Fees applied for,	
Special Damage or Repair Fee (if any)	£	:	:	19	
(per Sec. 88)					
Travelling Expenses (if chargeable)	£	:	:	Received by me,	
				19	
Second Surveyor's Fee (if any)	£	:	:		


 Surveyor to Lloyd's Register of Shipping.

Committee's Minute ✓ FRL-4 FEB. 1916 *Beck*
Character Assigned 1000

 © 2020
Lloyd's Reel
Foundation

W946-0007