

F.E.

Inspected by Chief Ship Surveyor

Received from Chief Ship Surveyor

15905

VESSEL'S NAME

Sheels Ardgaish

Rpt.

Sub

No. 17095

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

80.75

Depth "d" 17.5

Framing: Table No.

3. page 15.

Description

Bulk angle as approved

Longitudinal No.

31088.7

Proportions

Length = 10.4
Depth =

Ridge Deck Sheerstrake as approved.

The Bang Lungsun was report the survey has been completed.


This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed * 100A.1 (Steel) as recommended.

* 100A.1. (Steel)

2 DVs (Steel)

Call DB 334' 10296. A.P.T. 206

FK. 6BH. am. Lloyd's Reg. P24. B III. F 47



© 2020

Lloyd's Register
Foundation

W 968-0286