

Ship Surveyor

19/12/12

Received from Chief Ship Surveyor

NAME *At St Carronpark*

Rpt. *Std*

No. *25540*

is of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

to be endorsed to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

First entry

It is submitted that before this case receives the consideration of the Committee the Leith Surveyors should be informed that this vessel is returning from Sunderland to Methil after having had her machinery fitted, and that the only work carried out on the hull at Sunderland was the rivetting up of the Engine and Boiler casings.

They should be requested to give the case the necessary attention, and on completion of the work to forward a report on Form 8 in the usual manner with a view to the classification of the vessel.

19.12.12

AM

FRB

19.12.12



© 2019

Lloyd's Register
Foundation

W97-0016