

Surveyors _____

Received from Chief Surveyors _____

NAME WOOD S.S. "ALBERT METIN" Report Sea. No. 851.
(ex. "ORLEANDER")For the CHIEF SHIP SURVEYOR WILLIAM HENRIKSEN

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.

Survey _____

When due _____

The Committee have agreed to accept anchors tested at San Francisco, subject to the machine used being examined and reported upon.

* 12 A.1.

2 Dk. Well Dk.

Salted.

A.&C.P. P+B 145'. F36.

Subject to a Special Survey equal to a Half Time Survey at four and eight.

noted RR

M a.e.s.

18.8.19

JY

It is understood, the Deck & Hold, Beam Shefts are as approved but the Surveyors should be requested to state if this is so.

no letter

M



© 2020

Lloyd's Register
Foundation

W974-0053