

ARD REPORT on the


Jacobs.

Particulars as now reported inserted in Report submitted the Falmouth surveyors letter of 1st must be acknowledged and the owner be informed that to complete the conditions of freeboard assignment the following items ^{remain} require to be completed work.

① The Cuss bunker and coal shoot hatchways on the casing top to have battening arrangements ^{and coaming} as required by the Convention reasonably

② The coal hatchways in the bridge space being reasonably in accordance with the Convention requirements.

The Owner should be requested to state when and at what port it will be convenient to complete ~~examine~~ for the Society's surveyors to examine these items for the completion of the freeboard report.



© 2020

Lloyd's Register
Foundation

W984-0137

1/12/37

Coal Hatchways in bridge space.

As the coal bunker was full, these hatchways were not