

Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

EL'S NAME \_\_\_\_\_

"JAMES McGEE"

Report \_\_\_\_\_

N.Ns. \_\_\_\_\_

No. \_\_\_\_\_

5245

**For the ~~CHIEF SHIP SURVEYOR~~ and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

of Survey \_\_\_\_\_

Boiler Survey \_\_\_\_\_

When due \_\_\_\_\_

1.40.

Noted.

14.6.40

Subject to the donkey boiler not being used.



© 2020

Lloyd's Register  
Foundation

W486-0040

and boiler mountings opened up, overhauled, examined and refitted in place. Drain