

offered his services for this purpose and to whom and why they were declined

*Yes. Offered to Owners*

Society's Freeboard (if assigned) as painted on Ship and now verified

11, 20.

APR 1940

ived by Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

SSEL'S NAME "JANUS" Rpt. Got. No. 12893

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The Gothenburg Surveyors report t his vessel placed in dry dock, bottom coated and on account of damage through grounding, ice add during heavy weather, <sup>considerable</sup> ~~suitable~~ renewals or repairs have been effected to shell plating, framing etc (see approved plans attached).

It is submitted the vessel appears w orthy t o remain as classed with record of survey 3.40.

100 Al.  
3.40 Got.  
Carrying Petroleum in bulk.

*W.D.*

20 .4.40

W486-0129

*Discussed with Mr Thomson -*

*No further action required of L.S. repairs as required*



© 2020

Lloyd's Register Foundation