

Sp. 112764

Before this Case reaches consideration it is submitted
the Surveyors be referred to Secy's letter 10.6.44
As there is no reference in the report regarding the
ultimate paragraph in above letter on this matter,
the Surveyors remarks are awaited.

Inghis 1285 building
to class R.N.C.



© 2020

11.5.45

Lloyd's Register
Foundation

W986-0169

HOLDS.....

Height of Brackets at side above
leveling at top of frame

FLOORS AND

Spacing

RAISED UPPER DECK FORWARD