

2m.11.33.

2

Sent to Chief Surveyors

Received from Chief Surveyors

4 - MAR 1941

VESSEL'S NAME

HOUSATONIC

Report

LIV.

No. 115616

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)

(2<sup>ND</sup> No. 2 SURVEY PARTLY HELD.) DOCKING

When due

7-40


When proposed to be completed

Portion of Survey held, &c., Examination of anchors, cables + steering-gear (3-40)

Subject to lower portion of propeller post (E.W. 5-33, 3-35, 12-36, 11-37, 5-38 + 2-39) and stern frame sole piece (E.W. 3-40) being specially examined at the next dry-docking and to starboard chawse pipes being renewed at the Owners convenience.

(DOCKING DATE)  
2-41

*Wals*  
28-2-41



© 2020

Lloyd's Register  
Foundation

W484-0029