

by Chief Ship Surveyor

12/6/13

Received from Chief Ship Surveyor

EL'S NAME

At H No 104

Rpt.

Rpt

No.

8850

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey

First entry

It is submitted that before this case receives the consideration of the Committee the Hull Surveyors should be informed that this vessel has proceeded to their port for the purpose of having her machinery fitted, and to complete the survey on the hull the engine and boiler casings require to be riveted and the pillaring in the engine and boiler space to be completed.

They should be requested to give the case the necessary attention, and on completion of the work to forward a report on Form 8 with a view to the classification of the vessel.

L. 13/6/13

AP

RBM

12. 6. 13



© 2020

W989-0139

Lloyd's Register
Foundation