

(3)

of LEITH

25th January 1928

EVAN EDWARDS

the Builders of the vessel, survey the ss. "WESTBURY" of London, with view to ascertaining the nature and extent of damage stated to have been sustained on 3rd. December 1927 through striking the dock wall while leaving the Harbour at Leith after installing her machinery and Boilers.

On 7th December 1927 and subsequent dates while lying on mud flat and afloat in the Harbour of Burntisland surveyed the vessel found and recommended as follows:-

FOUND.RECOMMENDED.PORT SIDE.

The shell plating slightly set in in way of frame No.65, the damage extended for approximately 8'0" and affected three plates, one on D and one on E and one on F strake.

These shell plates to be faired in place.

The above recommendations were made with view to placing the vessel in as good condition as before the time of the accident.

On the 12th January 1928 while lying afloat in the Harbour of Burntisland the vessel was surveyed and it was found/



Lloyd's Register  
Foundation

W 99 - 00 24 (112) 2



2.

found that all repairs in connection with the damage in question have been satisfactorily carried out.

*Ern Egan*  
SURVEYOR TO LLOYD'S REGISTER.



© 2019

Lloyd's Register  
Foundation

IX 99-00 24(27) 10