

For the information of Surveyors and the Committee only.

Received at _____ Office, _____ 19

Lloyd's Register of Shipping.

(Report on Machinery, No. 31482 Port Sld)No. V1844.

ENGINE or BOILER VALVES or CONNECTIONS.

I have to report that the Details, as herein described, manufactured
by John A. Grant & Co. of Gardonsall.

for the Engines or Boilers No. 2803 being constructed by
North Eastern Marine Eng. Co. Ltd. of Sunderland.

have been inspected by me as set forth below, and found to be, so far as can
be seen, sound and free from defects.

These have been despatched to Sunderland.

Stamp Mark.

LLOYD'S TEST.

400 lbs.

No.

14-6-34

SldW. D. D. D.Glasgow.

ber and
Description.

2-2 $\frac{3}{4}$ " C.I. Double Spring Safety Valves.
2-2" C.I. Single Spring Safety Valves.

aulic Test:
s. per square inch.

400 lbs.

Tests, if any.

✓

when Inspected.

14-6-34.



© 2019

Lloyd's Register
FoundationSld.

1499-0051