

TONNAGE:—
GROSS 274

Built at BEVERLEY
Owners A & M. SMITH, LD.

By whom COOK, WELTON + GEMMELL, LD.
Owners' Address

When 1915

Inspected by Chief Ship Surveyor

Received from Chief Ship Surveyor 23 DEC 1946

VESSEL'S NAME "LOCH HOPE" Rpt. Lth. No. 21734

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey PERIODICAL SPECIAL SURVEY (D) 2nd. S.S. No. 3. due

THICKNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in ^{DECIMALS} of an inch.

STRAKE.	AMIDSHIP.				FORWARD.				AFT.				REMARKS.			
	Original Thickness.	Thickness by drilling.		Diminution if any.	Original Thickness.	Thickness by drilling.		Diminution if any.	Original Thickness.	Thickness by drilling.		Diminution if any.				
		Port.	Std.	Port. Std.		Port.	Std.	Port. Std.		Port.	Std.	Port. Std.				
SPAR SHEER STRAKE																
Strake below																
MAIN SHEER STRAKE	G	.62	.53	.53	.09	.09	.44	.56	.56		.44	.50	.50			
1st Strake below	F	.37	.37	.37			.37	.34	.34	.03	.03	.37	.31	.31	.06	.06
2nd " "	E	.44	.44	.56			.37	.31	.31	.06	.06	.37	.31	.31	.06	.06
3rd " "	D	.37	.37	.37			.37	.31	.31	.06	.06	.37	.31	.31	.06	.06
4th " "	C	.44	.37	.37	.07	.07	.37	.34	.34	.03	.03	.37	.31	.31	.06	.06
5th " "	B															
6th " "	GAZBOARD A															
7th " "																
8th " "																
9th " "																
10th " "																
11th " "																
12th " "																

Drillings at ends to be made in the vicinity of the peak bulkheads.


The LEITH Surveyors report this trawler placed in dry dock and the requirements of a PERIODICAL SPECIAL SURVEY (D) complied with.

The vessel now released from Government Service and reconverted for trawling services.

Shell drillings as shown above are satisfactory.

Repairs and renewals effected to shell, frames, centre keelson, bunkers, boiler stools, decks, beams and minor items.

15 fathoms of chain cable not verified with Certificate supplied to replace worn cable on board. A stream anchor, not verified with Certificate, supplied.



© 2019

Lloyd's Register Foundation

P.T.O.

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This vessel, having complied with the requirements of the "Periodical Special Survey" is now

Register Book
1915
Mac
(Including
H.M.
B.J.
T.S. C.
ned) as }
verified }
Alterat
in goo
Steelwo
case
place
and p
(P.T.O.)
M.
n Felt
Month
&c.
W ascertained
edges removed.
fter
of 2 h
if now ranged
105 fms me
on board,
length 105 f
Varps
Rigging

GROSS 274
UNDER DK. 239
109

Owners A. M. SMITH, LD.
Managers ✓

Owners' Address
(If not already recorded in Appendix)
Port belonging to

-2-

"LOCH HOPE"

An Echo Sounding Device has now been fitted.

It is submitted the vessel is eligible to remain as classed with record of docking survey 11.46 and to have notation of S.S. Lth.-11,46 (Dr.), subject to ^{Kege} stream anchor and 15 fathoms of chain cable being verified with Certificates.

11.46 Lth.)
S.S. Lth.-11,46 (Dr.)) subject.

Insert in R.B.:- (col 2)

E.S.D.

WOT
13.12.46. *BAM*

age
of Classifi
ly as in Regl
TEB.
d Survey.
ry and of
surveys.
R. 11, 3
- 12, 2
- 36.
ard (if as
ip and no
whom?
ession
place
heard
nts, co
found.
minea
ther Items :-
Copper, or
(State if
When fitte
Boats
Masts, Yarc
Condition,
(State if
Equipment
Anchors, M
Cables (Stat
" lengt
" Rule
Chain Lock
Hawsers &
Standing
Sails



© 2019

Lloyd's Register
Foundation
W990-0002.2/2

General Observations, Opinion as to Class, Recommendation, &c. :-
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book without fresh record of Survey. "to remain as classed in the Register Book without fresh record of Survey" "to remain as classed in the Register Book without fresh record of Survey" "to remain as classed in the Register Book without fresh record of Survey"