

11 OCT 1939

Surveyors

Received from Chief Surveyors

NAME

ALIDA

Report

Lw.

No. 113204

4 113225

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

2nd S.S. N° 3

When due


3,39.

Noted.

CEL. J.W.
11.10.39

to from SRL. - Shell plating (PKB) in way of after galleys to be dealt with at S.S.

to SRL - Structure in way of ESD. to be further examined when device is removed.



© 2020

Lloyd's Register
Foundation