



Lloyd's Register of Shipping,

47, Quai de la Fosse,

Nantes, 4th April 1927

LLOYD'S REGISTER
RECEIVED
-6 APR 1927
And
LONDON

THE SECRETARY
LONDON

Dear Sir ,

With reference to your letter of the 2nd inst. concerning the freeboards assigned to the s/s "KERVEGAN", we beg to inform you that from information we have just received from the French Custom's Officials who have worked out the tonnage measurement of the above vessel, the Under Deck tonnage stated to be 1788 t. has been measured as follows :-

Main Tonnage1585 t.	} 1708 tons + 12 tons for raised D.B. in mackerel space to normal D.B.
Tonnage of peaks	52 t.	
Tonnage of topsides ballast tanks	71 t.	
Tonnage of part of double bottom above normal floor	80 t.	

	1788 t.	


As the registered depth of 19.6' does not include the height of double bottom above normal floor, the under deck tonnage ought to be reduced by 80 tons, to 1708 t.

We should be glad to know of this affects the freeboards assigned to the vessel, and will keep the memoranda in the meantime.

The number of web plates fitted in No.4 hatchway is 5.

The "KERVEGAN" has now left St-Nazaire for Cardiff.

We are , Dear Sir,
Yours faithfully.


Lloyd's Register
Foundation
W9934-0154

frames, skin planking, or ceiling are of unusual thickness the breadth of vessel to inside ceiling should be reported if possible. ... obtaining an allowance for deck erections under Para. 11 where the sheer drops abaft amidships the height of the R.Q.D. is to be taken from the level of the top of the amidship beam. ... decked vessels the total standard ...

measured from top of ... at side.

Referred to the Chief Ship Surveyor

AS
-6 APR 1927

See other letter of
same date

Spl



© 2020

Lloyd's Register
Foundation

MEMORANDUM

THE DIRECTOR

THE DIRECTOR

THE DIRECTOR

THE DIRECTOR

frames, skin pl
elling should b
is obtaining a
s the height of

Sheer
idships
8 (e)]

ed as F

mean S

s of the

ternpos

tem.....

patient as co