

D REPORT on the

ss. "Keruegan"

It is submitted the Freeboards given on the accompanying form being those required by the Tables merit approval.


The Surveyors should stated the number of web plates fitted in N.W hatchway.

The Surveyors should inform the owners that the blanking off of the side-ballast tanks would not affect the freeboard assignment.

2 Plans to return in 2.4.27

2 / 2.4.27

W/S



87.B © 2020

1-4
31-3-27

Lloyd's Register
Foundation

W 9934 0158

4'-93/4"
= 3 1/4"
6 1/4"
03/4"
53/4"
7"
10 3/4"

103
7
4