

REGISTER, CARDIFF.

TELEPHONE: 7553 & 7554 CARDIFF.

Lloyd's Register of Shipping,

Empire House, Mount Stuart Square,

Cardiff, 25th. April 1944.

RECEIVED

26 APR 1944

And 27/4

3.

M.

Dear Sir,

Tanker "MARKAY".

With reference to the request contained in your letter of 21st. inst. copies of diagrams and calculations, with the necessary accompanying explanation will be forwarded as soon as they can be prepared, but some little time may elapse before this can be accomplished; the present diagrams and calculations are only in the rough and in a form requiring verbal explanation. We would however welcome a visit by Mr. Shepherd or Mr. Thomson any time within the next 3 weeks to examine the repair and discuss any point of special interest.

tary.

(The weld test apparatus for which the Committee made a grant is now ready for test and may also be examined).

I am, Dear Sir,
Yours faithfully,

C. A. Hicks

The Secretary,

LONDON.



© 2020

Lloyd's Register
Foundation

per sq. inch tensile and compressive (range of stress 10 tons) and the shear stress negligible; the ballast condition agreed by Mr. Finnigan and the Captain is therefore as indicated:-

Referred to the Chief Ship Surveyor.

P26.

26 APR 1944



© 2020

Lloyd's Register
Foundation