

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 7th 10th 19⁰⁸ When handed in at Local Office 19⁰⁸ Port of MIDDLESBROUGH-ON-TEES.

No. in Survey held at Middlesbrough-on-Tees Date, First Survey Sep 14 Last Survey Oct 1 1908

in Sup on the Wood, Iron or Steel S.S. Oneida

Master

YEAR. MONTH.

TONNAGE:-

GROSS 630

UNDER DK. 490

NET

Built at Grangemouth By whom Grangemouth & Grang. Mkd C When 1908

Owners Anglo-American Oil Co. Ltd

Port belonging to London

Owners' Address

(if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Yes Name of Dock

Destined Voyage London

WB=Cell DBor DBa feet; uE&B feet; f feet; }
total capacity tons. FPT tons; APT tons; MT feet tons. }

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

Last Report, No. Port

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified ft. tons.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? also whether any damage report was made, and, if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Completion of First Entry, see Fifth report.

How done: Coamings in way of boilers and engines now riveted up, all in order. Steam steering engine and gear tried under steam and found satisfactory.

SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE

Boats	Good	Stringers	Good	Dblg. Plates under Sounding Pipes	Good	Copper, or Y.M. of Wood Vessels	Good
Caulking of Decks	"	Inner Bottom Plating	"	Engine Room Skylights	"	(State if on Feet.)	"
Waterways	"	State if Tanks have been examined inside	"	Coal Bunkers, Open'gs, Lids, &c.	"	When put on, Month	"
Coamings	"	State if Tanks now tested	"	Scuppers	"	Boats	Good
Beams & Fastenings	"	Bulkheads	"	Cargo Hatchways	"	Masts, Yards, &c.	"
Outside Plating	"	Ceiling	"	Hatches	"	Condition, how ascertained	From deck
Caulking of ditto	"	Cement or Asphalt	"	Planing of Wood Vessels	"	(State if wedges removed)	210
Rivets	"	Rudder	"	Caulking	ditto	Sails	"
Breasthooks & Crutches	"	Windlass	"	Treenails	ditto	Equipment letter	"
Transoms	"	Have Pumps now been examined and found efficient?	"	Breasthooks & Stemson	ditto	Anchors, No. of	3/12 1/2
Reverse Frames	"	Have Sluice Valves now been examined and found efficient?	"	Transoms, Pointers, & Crutches	ditto	Cables (State if now ranged)	20
Boors	"	Have Watertight Doors now been examined and found efficient?	"	Timbers of Frame at openings	ditto	" length (on board)	"
Belsons	"			Ditto ditto at other places	ditto	" Rule length (per Table 22)	"
				Stringers, Clamps & Shells	ditto	Hawsers & Warps	Good
				Salting	ditto	Standing & Running Rigging	"
				(State if examined.)			

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,05," or "to remain as classed and to have record of survey, 1,05, and the notations of ss No. 1-05 and ptND05, &c."

This vessel is now in an efficient condition, shipth in my opinion for the class contemplated.

Survey Fee (per Section 24) £

Special Damage or Repair Fee (if any) £

Travelling Expenses (if chargeable) £

Bond Surveyor's Fee (if any) £

Fees applied for,

19

Received by me,

19

Committee's Minute

FRI. 16 OCT 1908

Character Assigned

See minute on S.G. report.

Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2020

Lloyd's Register Foundation

W 996-030