

# Lloyd's Register of Shipping.

Ship's Name ONEIDA

Official No. 125733

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines  
in MAY, 1932.

1. There are no openings on the freeboard deck within the bridge space.
2. There are no scupper pipes led to the bilges
3. Scuppers from the freeboard deck are provided with storm valves at the ship's sides.
4. Two openings in bridge forward bulkhead, each 4'0" x 3'0", sills 15", openings closed with portable plates and hook bolts. (Bel. May, 1937).

*A.B. 21.5.37.*

