

Last Report, No. 20896. Port Syd.

£100A.1
Aving Dr
11/10/1

(Including date
+ LMC
BS
TS (CL)

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Survey should be summarized. State clearly the cause of Defects if any, and in detail the nature and extent of Defects.

46. mn

21 OCT 1947

Inspected by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME THEMISTOCLES REPORT Lon. No. 115550

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

A General Examination became due 6,47.


The class is subject to indented plating etc. on starboard side of No. 1 hold, to No. 9 after tank end, to indented sheerstrake plate (p.s) and to set in bulwarks on forecastle (s.s) being dealt with at the Owners' convenience, and to (a bower anchor being supplied).

Vessel is laid up at Blackwater pending survey.

The LONDON Surveyors report the vessel examined afloat and found efficient for voyage in ballast condition to River Clyde, where, it is stated, she is to be broken up.

It is submitted NO ACTION be taken pending further information regarding the vessel's future.

16.10.47



© 2020

Lloyd's Register Foundation

FLOORS	Have watertight DOORS been examined and found efficient? <u>Yes</u>	Transoms, Pointers & Crutches	ascertained (ages removed.)
Keelsons	Have Ventilators and their Coamings been examined and found efficient? <u>Yes</u>	Timbers of Frame at openings	Rule length
Stringers	Air and Sounding Pipes <u>Efficient</u>	" " at other places	Chain Locker
Inner Bottom Plating	Double Plating under Sounding Pipes	Stringers, Clamps & Shelves	Hawsers & Warps
Have the Tanks been examined internally? <u>See "B" to</u>		Salting	Standing and Running Rigging
Have the Tanks been tested?			

Ref
d) as }
ified } 11
of Freeb
th. 14
er Affl
is, Acc
an as
board ver
d for in
shy In
opies ab
lot deat
s time
Felt.)
Month
Sup
&c.
ascertained
ages removed.)
R
L
row ranged)
(on board) Stab