

to Chief Surveyors _____

Received from Chief Surveyors _____

SEL'S NAME "British Merchant" Report Gls. No. 42289

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

re of Survey First Entry When due ✓

✱ 100 A1 (Steel) "Carrying Petroleum in Bulk."
2 Dks (Stl).

Cell DB u E+B 67'248t DTF 45'701t FPT 168t APT 240t
FK, 10BH to upper Dk, GBH to 2nd DK. pt Cem. Lloyd's A+CP.
P 116' B 35' F 49' Mch. aft.



© 2020

Lloyd's Register
Foundation
9/11/22.