

# Lloyd's Register of Shipping.



.....25th May, 1948.....

part of the  
Surveyed the Boiler and Machinery of the SS. "DEAN EMERY"

Harbour, Aruba, N.W.I. on the 22nd May, 1949 and subsequently  
on account of Boiler repair.

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I have

Recommended that the record of xxxxxxx vessel be continued

as classed without fresh record of survey.

be made in the Register Book in the case of this vessel.

W. P. Holmes.

Engineer Surveyor to Lloyd's Register.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."