

Hold Beams No	Space Average	11	15	12	10	Sheer Strakes	4
	11 feet		"	"	"	Plank Sheers	

See

Westford 28th May 1851

The owner of this ship, fully expects
 that this vessel, "Falcon", will
 be restored to the first accepta-
 ce of first class for what
 ever time the Committee may
 think she is entitled to as
 everything has been done that
 I required, I am loth to give my
 opinion on the form, as you may
 place her on a higher grade than ~~me~~
 as I consider her entitled to a
 higher grade, I beg leave to inform
 you that several vessels has been kept
 here at this port, & taken I could not
 get them a higher grade than F. went
 to other ports in england, & those had then
 placed on higher grade.

Shelf Pieces of spruce one WEX1031-0164
 Fastenings.—To Hold Beams all larch fastened with iron nails



@2021


Lloyd's Register
Foundation

There is no owner of Ships at this
port will go to the expense of a
Special Surveyor, as the traveling
expenses & from Belfast the conve-
nient being High.

Your obedt Servt

A Deacon

To
Charles Graham Esq - Surveyor



© 2021

Lloyd's Register
Foundation