

Dear Sir

I expect the enclosed will fully explain the error in measurement of vessel. I had measured her while building & seeing the Customs return corresponding with it, I did not examine the return given me by the foreman of the yard those broad hanging knees are equal to plates, and the extra clamps & stringers should be allowed for. On this vessel being classed I will send you the half yearly acct- to 1 July

Yours &c
Rearson

Wexford
3rd July 1854

© 2021

Lloyd's Register
Foundation

WEX 1031-0231

[Faint, mostly illegible handwritten text in cursive script, likely from an 18th-century letter.]



© 2021


Lloyd's Register
Foundation