

Wesford 4/80

14 April 1880.

Specification of Cables and Anchors
on Board the Schooner Ruby of Westford
also tested at New Bedford Mass. Ruby
No. 4132 for 60 fms of 1/2 inch short link chain

No. 4532 for 45 1/2 fms of 7/8 inch short link chain

No. 3837 for 30 1/2 fms 7/8 - " " "

No. 6718 for anchor 4.2.21 Newbern
Swiss
Stroke 1.1.26.

6720 for anchor 1.2.7 ditto
Stroke 2.7

8719 for anchor 5.2.4 ditto
Stroke 1.2.24

~~3837~~ for

7148 for 90 fms of 1/2 inch close link

I have reexamined these chains and
anchors and find them all correct there is
one shackle of 7/8 chain added to the
60 fms of 1 inch so that the vessel has more
chain than the Rules require

Respectfully

Wm. Westford



© 2021

Lloyd's Register
Foundation

WEX 1031-0243

10/4/80.

to D. S. S. S.
M

1880

Wesford, 14 April

Mr. Sparrow,

Rec. 16,

Am?

Particulars of
Chains & Anchors
of Ruby.



© 2021

Lloyd's Register
Foundation