

19 OCT 1935

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "OLIVEBANK" Rpt. Skm. No. 4099

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(* The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

This vessel is 43 years old.

The Stockholm Surveyors report this ship examined afloat, the requirements of a S.S.No.2, due 11,35, partly complied with, repairs or renewals in fore peak and to yards and minor repairs carried out.

To complete the survey the bottom, anchors, chain cables and chain locker and the internal structure under ballast to be examined.

It is submitted the vessel appears worthy to remain as classed without record of survey.

PLATING to be DRILLED, ^{12 years from 10.31} when vessel is 54 years old, or at next Special Survey thereafter.

Yes see letter 17.10.37

Handwritten signatures and date 9.10.35

It is concluded that in addition to the items stated to remain to complete the survey the internal examination of structure under ballast should be included.



© 2021

Lloyd's Register Foundation