

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 28 March 1912 When handed in at Local Office 19 Port of Hamburg.
 No. in Reg. Book. 20 Survey held at Hamburg. Date, First Survey and Last Survey 15 March 1911
on the Wood, Iron or Steel 4th Shk Pamir Master H. Horn
 TONNAGE: Built at Hamburg By whom Holm & Voss When 1905 YEAR MONTH
 GROSS 2020 Owners F. Loeiz Port belonging to Hamburg
 UNDER DK. 2789 Owners' Address
 NET 2777 (If not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? yes Name of Dock Blohm & Voss Destined Voyage Out coast

WB=CellDBorDBa feet; uE&B feet; f feet; }
 total capacity tons. FPT tons; APT tons; MT feet tons. }

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
<u>100 A 1</u>		
<u>5. 11.</u>		
<u>S.S. Ham No 1-09</u>		

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thickness of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 12100 Port Ham

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Condition:

*The vessel examined in dry dock, the bottom found cleaned and coated in good condition.
 The rudder examined and found satisfactory.*

SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Faired or Repaired ...								
Faired or Repaired in place ...								

PRESENT CONDITION OF THE

Decks <u>Good</u>	Stringers <u>Good</u>	Dblg. Plates under Sounding Pipes <u>✓</u>	Copper, or T.M. of Wood Vessels (State if on Belt.) <u>Good</u>
Caulking of Decks <u>" "</u>	Inner Bottom Plating <u>✓</u>	Engine Room Skylights <u>✓</u>	Boats <u>Good</u>
Waterways <u>" "</u>	State if Tanks have been examined inside <u>✓</u>	Coal Bunkers, Open'gs, Lids, &c. <u>✓</u>	Masts, Yards, &c. <u>" "</u>
Coamings <u>" "</u>	State if Tanks now tested. <u>✓</u>	Scuppers <u>Good</u>	Condition, how ascertained <u>from deck</u>
Beams & Fastenings <u>" "</u>	Bulkheads <u>✓</u>	Cargo Hatchways <u>" "</u>	(State if redges removed) <u>✓</u>
Outside Plating <u>" "</u>	Ceiling <u>✓</u>	Hatches <u>" "</u>	Sails <u>" "</u>
Caulking of ditto <u>" "</u>	Cement or Asphalt (State which.) <u>✓</u>	Planking of Wood Vessels <u>✓</u>	Equipment letter <u>X</u>
Rivets <u>" "</u>	Rudder <u>Good</u>	Caulking ditto <u>✓</u>	Anchors, No. of <u>complete</u>
Breasthooks & Crutches <u>✓</u>	Steering gear and its connections <u>" "</u>	Treenails ditto <u>✓</u>	Cables (State if now ranged) <u>✓</u>
Transoms <u>✓</u>	Windlass <u>" "</u>	Breasthooks & Stemson ditto <u>✓</u>	" length (on board) size <u>✓</u>
Frames <u>✓</u>	Have Pumps now been examined and found efficient? <u>✓</u>	Transoms, Pointers, & Crutches ditto <u>✓</u>	" Rule length size <u>✓</u>
Reverse Frames <u>✓</u>	Have Sluice Valves now been examined and found efficient? <u>✓</u>	Timbers of Frame openings ditto <u>✓</u>	Hawser & Warps <u>stated complete</u>
Floors <u>✓</u>	Have Watertight Doors now been examined and found efficient? <u>✓</u>	Ditto ditto at other places ditto <u>✓</u>	Standing & Running Rigging <u>Good</u>
Keelsons <u>✓</u>		Stringers, Clamps & Shells ditto <u>✓</u>	
		Salting (State if examined.) ditto <u>✓</u>	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,10," or "to remain as classed and to have record of survey, 1,10, and the notations of ss No. 1-10 and ptnD10, &c."

This vessel appears, as far as examined, to be in a sound and efficient condition, in my opinion eligible to remain as classed and to have record of Survey 3. 12.

Survey Fee (per Section 29) £

Special Damage or Repair Fee (if any) (per Sec. 29) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

10

Received by me,

10

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

TUE APR 2-1912

Character Assigned

100 A 1



© 2018

Lloyd's Register Foundation