

No. 137Survey held at LiverpoolDate Sept - 15184 2on the BrigMaster BrownTonnage 270Built at LiverpoolWhen built 1838By whom built —Owners Cairns & Co.Port belonging to LiverpoolDestined Voyage GalvestonIf Surveyed Afloat or in Dry Dock —Original Survey, No. 2520Port of Liverpool2848, 3172, 3612, 4155Classed Brig & Gun

The Surveyor is required to state the present Condition of the

Decks GoodTransoms —Capstan —Upper Deck Beams & Fastenings —Timbers of the Frame —Pumps GoodLower Deck Beams & Fastenings —Topsides —Masts, Yards, &c. All NewSpirketting —Wales —Sails 3 Well foundPlank Shears —Counter —Cables —Waterways —

Plank and Treenails

(Outside to the Water's Edge.)

Anchors No. of 3 Bow 1st 2ndHatchway Comings —Rudder —Standing & Running Rigging New StandingBreasthooks —Windlass —Copper —

General Observations and Opinion,

as required by the Instructions,

Appears in a condition for the safe conveyance of any perishable cargoes to & from all parts of the world & recommended hereto continue as stated

Committee Minute 20th September184 2Character assigned Brig & Gun

Supreme Court  
James W. Wadsworth  
50445



© 2018  
Lloyd's Register  
Foundation