

IRON 8/12  
**ANNUAL SURVEYS.**

37402

No. 39 Survey held at London Date Jan'y 26<sup>th</sup> Feb'y 1<sup>st</sup> 1871  
on the Iron Ship Ramsey Master E. Hunt  
Tonnage 809 Built at Isle of Man When built 1863  
By whom built Gibson Owners Mackay & Co.  
Port belonging to Liverpool & London Destined Voyage Australia  
If Surveyed Afloat or in Dry Dock Pontoons &

Last Survey, No. 7896 Port of Iron. Classed <sup>11</sup>/<sub>11</sub> A. 1. S.S. no 1/67.  
2/1

The present Condition of the

Decks	good	Freeboards	Rivets where seen good	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Sails	"
Planksheers	"	Keelsons	"	Anchors No. of 3 4 1 S. 2 K	"
Sheerstrakes	"	Clamps and Shelves	"	Cables	"
Topsides	"	Ceiling	"	Hawsers and Warps	"
Wales	"	Rudder efficient	"	Standing & Running Rigging	"
Plank (Bottom) and Counter	"	Copper	When put on		

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good  
Cleaned the bottom and coated it with Gays Pat<sup>l</sup>. I am of opinion  
she is entitled to remain as classed A. 1.  
Samuel Presnall.

Committee's Minute 10<sup>th</sup> February 1871  
Character assigned <sup>11</sup>/<sub>11</sub> A. 1. J.P.

Certificate (if required)

No. 57 Survey held at London Date 28<sup>th</sup> Jan'y Feb'y 8<sup>th</sup> 1871  
on the Ironship Saint Mungo Master W<sup>m</sup> Watson  
Tonnage 1375 Built at Hull When built 1865 2 mth  
By whom built Hunter Iron Works Owners Gilmour &  
Port belonging to Glasgow Destined Voyage Sydney  
If Surveyed Afloat or in Dry Dock Thames dry dock and East India Docks

Last Survey, No. 7897 Port of Iron. Classed <sup>11</sup>/<sub>11</sub> A. 1. S.S. no 1/70.  
3/70

The present Condition of the

Decks	good	Freeboards	Rivets where seen good	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Sails	"
Planksheers	"	Keelsons	"	Anchors No. of 3 4 1 S. 2 K	"
Sheerstrakes	"	Clamps and Shelves	"	Cables	"
Topsides	"	Ceiling	"	Hawsers and Warps	"
Wales	"	Rudder efficient	"	Standing & Running Rigging	"
Plank (Bottom) and Counter	"	Copper	When put on		

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good  
Cleaned the bottom and recoated it with McGinnis's Pat<sup>l</sup> and one of  
tallow. - filled a Stop Cock in Head Pump. - She is in good condition and I am  
of opinion she is entitled to remain as  
classed A. 1.  
Samuel Presnall.

Committee's Minute 10<sup>th</sup> February 1871  
Character assigned <sup>11</sup>/<sub>11</sub> A. 1. J.P.

Certificate (if required)



© 2018  
Lloyd's Register  
Foundation