

ANNUAL SURVEYS.

No. in Reg. Book. 59 No. 1 Survey held at London Date, first Survey 1877 Last Survey April 3^d 1877
 on the S Ramirez Master Cater
 Tonnage 767 Built at Ile of Man When built 1863 & no. 2
 By whom built Gibson Owners Jaylor Pettit & Roberts
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 16315 Port of Iron Classed AV 5.76
 Present Condition of the Decks Good Treennails Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Coated When put on When
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom Scraped & Coated

She is now in an efficient state of repair & entitled to remain as classed

Committee's Minute 20th April 18 77
 Character assigned AV

Senhouse Martin
 Surveyor to Lloyd's Register of British and Foreign Shipping
 Certificate (if required)
 © 2018 Lloyd's Register Foundation