

IRON

ANNUAL SURVEYS.

No. 40713 Survey held at London Date, first Survey 2nd July Last Survey 5th Aug 1881

No. in Reg. Book. 66 on the Iron Bk Ramsey Master H. L. L. L.

Tonnage { Net 767 Built at Isle of Man When built 1863 2
Gross 821
Under Dk. 661

By whom built Gibson Owners J. R. Harper

Port belonging to London Destined Voyage Brisbane

If Surveyed Afloat or in Dry Dock Rugg's dry Dock & Afloat
(State Name of Dock.)

Last Survey, No. 27343 Port of Iron

Present Condition of the Decks Good Treennails Rivets Good

Waterways — Breasthooks and Stems —

Comings — Transoms, Pointers, and Crutches —

Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —

Lower Deck Beams & Fastenings — Ditto ditto at other places —

Planksheers — Keelsons —

Sheerstrakes — Clamps and Shelves —

Topsides — Ceiling —

Wales — Rudder —

Blank (Bottom) and Counter — Copper or Y.M. Cement When put on 1863

Engine Room Skylights — Caulking of Bottom, Deck, & Waterways Good

Coal Bunkers, Openings, Lids, &c. — Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.

Bottom repainted. Rudder pintles bucked. She is now in good condition and eligible in my opinion to continue as Classed

Committee's Minute 15/8/81 Tuesday, August, 16th 1881

Character assigned — Surveyor to Lloyd's Register of British and Foreign Shipping W. B. Davy
Certificate (if required, to be sent as per margin) —

The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.

© 2018

Lloyd's Register Foundation