

COPY.

Hamburg Report Nr. 14522

Lloyd's Register of Shipping.



Port of Hamburg

25th of September, 1925.

This is to Certify that I have

XXXXXX XX

Iron Sc. 3 Mast Sr.

Surveyed the Boiler and Machinery of the

"BETTER" 876 Gross tons of Leith afloat at Hamburg

for damage and damage repairs to H.P. cylinder cover. XXXXX

and that I have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report stating that all

recommendations made by me in connection therewith have

been carried out to my satisfaction, and that I have

Recommended that the record of survey be continued, subject

to permanent repairs to H.P. cylinder cover being carried out within a month time, say end of October, 1925.

XXXXXX

be made in the Register Book in the case of this vessel.

K. Gracovsk

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book, for any error or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.



© 2018

Lloyd's Register
Foundation