

# ANNUAL SURVEYS.

30500

No.

Survey held at

London

Date

1<sup>st</sup> Oct<sup>r</sup> - 3<sup>rd</sup> Nov<sup>r</sup> 1869

on the

Ship "Thermopylae"

Master

R. Remball

Tonnage

947

Built at

Aberdeen

When built

1868

By whom built

Ward

Owners

Hompson & Co

Port belonging to

Aberdeen

Destined Voyage

Australia

If Surveyed Afloat or in Dry Dock

in the Port of Aberdeen (Victoria Dock) and Afloat.

Last Survey, No.

29341

Port of

London.

Classed

17 A1

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Reetrakes

Topsides

Wales

Plank (Bottom) and Counter

General Observations and Opinion.

Personals Hastings & Co.

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

1868

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Caulking of Bottom, Deck, and Waterways

Good where examined

Patched Copper Metal Sheathing iron bands in Liboom repaired.  
is now in good and efficient condition. and in  
my opinion eligible to remain as Classed 17 A1  
Committee's Minute 18<sup>th</sup> November 1869

Character assigned..

17 A1



© 2018

Lloyd's Register  
Foundation

Certificate (if required)